

25X1 CENTRAL INTELLIGENCE AGENCY 25X1

INFORMATION REPORT

4363

COUNTRY Germany (Russian Zone)

DATE DISTR. 30 Nov. 1951

SUBJECT Radar Installations in the Eastern Sector
of Berlin

NO. OF PAGES 1

25X1

PLACE ACQUIRED

NO. OF ENCLS. 2 (2 pages)
(LISTED BELOW)

DATE OF INFO ACQUIRED

25X1

SUPPLEMENT TO
REPORT NO.

25X1

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE
OF THE UNITED STATES WITHIN THE MEANING OF THE SPIONAGE ACT 50
U. S. C., 31 AND 32 AS AMENDED. ITS TRANSMISSION, DISCLOSURE, OR REVELATION
OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PRO-
HIBITED BY LAW. REPRODUCTION OF THIS FORM IS PROHIBITED

THIS IS UNEVALUATED INFORMATION

25X1

The following attachments are sent to you on loan. Please return by
14 December 1951.

A. Report on radar installations in the Eastern Sector of Berlin as of
12 June 1951 (1 page).

B. Photocopy of sketches 25X1

WS

JUN 8 1951 MM 52

25X1

--	--	--	--

25X1

CLASSIFICATION

SECRET

STATE	NAVY	NSRB		DISTRIBUTION				
ARMY	AIR			OSI				

25X1

25X1

*THIS IS A
2nd ENCLOSURE TO
DO NOT DETACH*

GERMANY (SOVIET ZONE)

Radar Installations

25X1

1. Since early April 1951 the apparatus shown on the attached sketch (photocopy) has been in position on a flat-roofed building situated in the Soviet Zone of Berlin about one kilometer away from the building

25X1



(which is not in the Soviet Zone).

25X1 2. It appears to be "aiming at" the building.

25X1

25X1

25X1



zwischen den beiden Füßen ist ein
schweres Eisenprofil dem Flachdach
entlang mit einem oben